

### Tools required for installation




Electric drill



Drill bit  
(Φ6)



Tape measure  
(3m~5m)



Silicone



Pencil



Screwdriver


### Cabinet



6A



8B



2D



2E

